

CRESTVIEW CONDOMINIUMS

Exterior Building Repair Project Summary

7/28/2022



Presentation Outline

- Who is J2?
- J2's Scope of Work at Crestview to date
- Project Goals
- Scope of Repair Recommendations
 - Existing and proposed materials for main building components
- Project Budget
- Next Steps



Who is J2?

The Building Doctors



WHO WE ARE


• J2 is an engineering firm specializing in the evaluation, design and overseeing the remediation process of existing buildings.

WHAT WE DO

 We are building doctors. We diagnose, prescribe, and treat existing buildings that have been damaged by harsh environments, defects, age, disaster, or neglect.

WHY THIS IS IMPORTANT

- We provide leadership and hope to an oftentimes confusing and discouraging process.
- We speak the languages of construction, project management, insurance recovery, litigation support, and finance.
- We represent the Association through the repair process





J2's Scope of Work to Date

- Perform building envelope evaluation
- Assist with temporary deck repair recommendations
- Assist with leak repairs
- Draft Scope of Repair documents (Plans and Specs)
- Conducted a competitive bid process
- Performed follow up deck inspections



More on the Competitive Bid Process:

- Pre-qualified 3 contractors
- Bid walk
- Answer contractor questions
- Bid review/analysis
- Contractor interviews and Board/Committee meetings
 - ClearCut was selected as contractor
 - Low Bid
 - Most knowledgeable about the buildings
 - Best fit for the project



Remediation Project Goals

- 1) Life Safety
 - Decks
- 2) Reconcile Exterior Building Deficiencies
 - Reduce emergency leak repairs
 - Reduce maintenance costs
 - Existing systems are not maintainable
 - Will not last their expected useful life
- 3) Reconcile Reserve Study (Maintain/Repair/Replace)
 - Avoid future shortfalls/assessments



Scope of Repair Recommendations

- Roof
- Cladding (siding, stucco, manufactured stone)
- Windows
- Decks



Roofing

Existing Assembly:

"Standard" asphalt shingles

Proposed Assembly:

- Polymer-modified shingles
 - Heavy weight
 - Impact-resistant
 - Rubberizing polymers improve performance in temperature extremes
 - Increased granule adhesion
 - Enhanced crack resistance
- Ice Melt System
 - "Commercial Grade"
- Warranties
 - Roofing: 50 year limited transferable warranty against manufacturing defects;
 10 year "SureStart" warranty
 - o Ice Melt: 10 year warranty; 20 year expected useful life





"Attic" Venting

Existing Assembly:

Existing roof assembly is not vented adequately


Proposed Assembly:

- Insulated nail base installed on top existing roof sheathing.
 - Less invasive
 - Ensures proper venting
 - Increases shingle life
 - Adds insulation value
 - Decreases condensation risk
 - Decreases ice damming risk












Granule loss and shingle damage



Improper roof-to-wall integration




Granule loss and shingle damage





Improper diverter resulting in water intrusion at walls





Sealant dependent coping (and improper sealant).



Improper mounting penetrations at rooftop mechanical equipment.





Improper and deteriorating flashing



Cladding

Existing Siding:

- Stucco
- Wood siding
- Manufactured Stone veneer

Proposed Assembly:

- Replace stucco with new stucco with proper joints
- Replace wood siding with fiber cement siding with a factory finish
- Replace stone veneer with similar material
- Add drainage medium for drainage and drying





Fiber Cement Siding – Wood Look

Replace wood siding with fiber cement siding prefinished to look like stained wood

 20 Year limited fade coating warranty in addition to manufacture's substrate warranty

Lower maintenance than wood siding

Readily available





Stucco and Stone Veneer

Replace stucco and stone veneer with new stucco and stone veneer over drainage medium/rainscreen system

- Stucco 7 year material warranty
- Stone Veneer material warranty varies my manufacturer, 10 year installation warranty by Clearcut
- Ventilated air space allows water to drain and allows wall to dry
- Dynamic sealant joints at material transitions
- Crack control joints








Deteriorated sheathing and WRB under deck ledger; stucco cracks








Open void into wall cavity at deck to wall locations








Water damaged WRB and sheathing







Deterioration of manufactured stone veneer; mortar/attachment failure of veneer







Manufactured stone veneer assembly failure







Weathered wood trim

High maintenance horizontal siding; prone to cracking, cupping and finish deterioration



Windows

Remove and replace existing windows

- Transferable limited 20/10 warranty
 - 20 years for IGU's (glass/visibility)
 - 10 years for non-glass/operation components
- Removal required for proper installation
- Frame damage expected due to improper detailing
- Higher performance grade
- High quality vinyl (sun/temperature)
- Energy efficiency
- Venting






Window Detailing

Proper Detailing:

- Interior air seal
- Exterior weather lap
- Redundant means of drainage
- Expansion/contraction





Windows – Example Photos





Omitted movement joints between window frames and adjacent cladding

Windows – Example Photos



Omitted WRB behind window trim

Omitted SAF and sealant; improper fastening



Decks

Existing:

- Non-preservative treated structural framing
- Twisting/splitting/checking
- Paint failure
- Settling (inadequate soil bearing)

Proposed:

- Preservative treated and stained framing
- GLB posts/beams; "appearance grade"
- Metal guards
- Underpinning





Deck Underpinning

Stabilize footings by "underpinning" decks with helical piers bolted to existing foundation





Deck Guards

Replace wood guards with powder coated aluminum guards

- Low maintenance
- 10 year finish warranty provided by Clearcut
- Long expected useful life
- Contemporary look





Deck Timbers

Replace existing framing with new preservative treated GLB timbers

- Appearance grade
- Straight and true
- Treated to proper standards
- Stained (not painted)






Deck Boards

Replace existing deck boards with new composite boards

25 year warranty (Trex)









Lower floor patio wall pulling away from building due to foundation settling







Decayed deck joists (35% +/-)







Decayed deck beams (10-20%)







Decayed deck columns (30%+)







Wood decay at base of column





Deck connection failures





Weathered guardrail wood caps and paint

Inadequate guard attachment

Before and After



Existing



Proposed


- Stucco control joints
- No "live edge" on siding
- Guard rail material
- Stained "appearance grade" deck timbers

Thicker roof fascia



Local Architecture





Silverado Lodge

Project Budget

How much will this cost?

Total Project Cost: \$9.1M

 Includes construction costs, contingencies, and all related fees

"Guarantees" price for 2023/2024 Construction



Next Steps

- Funding
- Finalize Construction Documents and Construction Contract
- Pre-Construction Activities
 - Submittal process
 - Material purchase/storage
- Construction Mobilization Spring 2023
- J2 will monitor construction
 - Design Professional of Record
 - Additional quality assurance
 - Reviewing payment applications, change orders, budget, schedule, etc.





THANK YOU!

Ryan Paddock, P.E.



ryanp@j2consultants.com

